

To Remove Bolts/Screws	Use Drill Bit Size	Shank Diameter	Point Diameter
3/32" to 5/32"	5/64"	1/8"	0.060"
5/32" to 7/32"	7/64"	3/16"	0.080"
7/32" to 9/32"	5/32"	1/4"	1/8"
9/32" to 3/8" & 1/8" pipe	1/4"	5/16"	3/16"
3/8" to 5/8" & 1/4" pipe	1/4"	7/16"	1/4"